


# VIAGRAM

Information Note



Subject: VIATRON Maintenance Policy for  
IBM Model 029 Card Punch

No: 22

Date: April 1, 1970

Several dealers and customers have requested clarification of the relationship between VIATRON and IBM with respect to maintenance of IBM machines attached to VIATRON terminals.

An authorized IBM representative has examined an IBM Model 029 Card Punch located at VIATRON Computer Systems Corporation at 111 Terrace Hall Avenue, Burlington, Massachusetts, to which a VIATRON Model 6001 Card Reader/Punch Adapter is attached. He found that this attachment does not affect the safety level of the IBM machine. Consequently, normal IBM maintenance rates apply to 029 Card Punches connected to System 21 by means of the VIATRON Card Reader/Punch Adapter.